

Certificate

Breakthrough Management Quality Registrar (BMQR)

Certifies that the Quality Management System of

ULTRAMAX HYDROJET PVT. LTD.

Unit I: Plot No. AC – 31/4-A, 6th Main Road, SIDCO Industrial Estate,
Thirumudivakkam, Chennai – 600 044. Tamilnadu, India.

Unit II: No. 98/7, 13th Cross Street, SIDCO Industrial Estate,
Thirumudivakkam, Chennai – 600 044. Tamilnadu, India.

has been assessed and found to be in accordance with the requirements of the quality standards

ISO 9001:2015

for the following scope of certification

DESIGN, DEVELOPMENT, MANUFACTURE, INSTALLATION, COMMISSIONING, AND SERVICE OF WASHING/CLEANING PLANT, INDUSTRIAL CLEANING SYSTEM, PARTS CLEANING PLANT, DEGREASING EQUIPMENT AND ITS RELEVANT ACCESSORIES, COACH CLEANING PLANT, WATER RECYCLING & EFFLUENT TREATMENT PLANT, HIGH PRESSURE WASHER & ITS ACCESSORIES, SEWER JETTING AND VACCUM SYSTEM, STEAM CLEANER, HOT WATER JET CLEANER, VACCUM CLEANER, FOGGING-MISTING, HUMIDIFICATION SYSTEM, SURFACE TREATMENT PLANTS, PAINTBOOTH & DRYING/BAKING OVEN, AUTOMATIC AHU FILTER CLEANING MACHINE, FIRE FIGHTER SYSTEM, AUTOMATIC COMPONENT AND ULTRASONIC CLEANING M/C'S/PLANTS, HOT & STEAM CLEANER, HIGH PRESSURE POWER PACK, AUTOMATIC COACH WASHING, HYDRAULIC LIFTING SYSTEM / HYDRAULIC POWER PACK, HYDRAULIC AUTO DOOR SYSTEM, WET SAND BLASTING, BEARING CLEANING PLANT, AXLE BOX CLEANING PLANT, ENGINE BLOCK WASHER, HOT PHOSPHATING PLANT, ROTARY LOBE PUMP, TROLLEY MOUNTED MOBILE SEWAGE EVACUATION MACHINE, AUTOMATIC BOGIE WASH PLANT, BOGIE COMPONENT CLEANING PLANT, WHEEL SET WASHING PLANT, POSITIVE DISPLACEMENT REVERSIBLE ROTARY LOBE PUMP OF CAPACITY 150 LITRES PER MINUTE OR ABOVE, CTRB OVERHAULING PLANT, INDUSTRIAL CLEANING PLANTS, WATER PRESSURE TESTING MACHINE UP TO 2800 BAR

Further clarifications regarding the scope of this certificate and applicability of ISO 9001:2015 requirements may be obtained by consulting the organization.

Original Certification Date : 20/08/2013
Current Certification Date : 04/08/2022
Seventh Surveillance Due on : 03/08/2023
Eighth Surveillance Due on : 03/08/2024
Certificate Expiration Date : 03/08/2025



Surveillance Audit

Due On 03/08/2023 Due On 03/08/2024



This certificate is invalid if surveillance audit is not completed



Certificate No: AB09IS131895/R5



Stamp

For BMQR

No:5, 2nd Floor, Sathyamoorthy Road, Thiruvalléeswarar Nagar, Thirumangalam,
Anna Nagar West, Chennai - 600 040. Tamilnadu, India.

email: iso@bmqr.com, Web : www.bmqr.com

PH- 044-26152595



The certificate will remain current subject to the company maintaining its system to the required standard(s). This will be monitored regularly by BMQR Certifications Pvt. Ltd., This Certification details and effectiveness are listed at www.bmqr.com. Registration does not assure the quality of products produced by a Quality System. This Certificate is granted based on the limited sampling audit as per ISO 19011:2011 and BMQR is not responsible for client's failure to maintain documented quality system. This certificate is the property of BMQR Certifications Pvt. Ltd, and to be returned upon request.